













Measuring probes

ACCESSORIES

		P2i	P2iP	P5i	P5iP	P2	P5	P10	P25	P50
	905.2204					•	•	•	•	•
	901.2003						•			
	901.2004							•		
	901.2005						•	•		
	901.2012						•	•	•	•
	901.2013						•	•	•	•
	901.2014						•	•	•	•
	901.5110	•	•							

Measuring probes

ACCESSORIES

		P2i	P2iP	P5i	P5iP	P2	P5	P10	P25	P50
	901.5002 Cable 1.5 m							•		
	901.5012 Cable 1.5 m								•	
	901.5022 Cable 1.5 m									•
	901.5032 Cable 1.5 m bent							•		
	901.5042 Cable 1.5 m						•			
	901.5052 Cable 1.5 m bent						•			
	905.2231 Adapting socket + screw	•	•	•	•	•	•	•	•	•